## GOVERNMENT OF ANDHRA PRADESH ROADS AND BUILDINGS DEPARTMENT

From, Sri.Y.V.Kishore Babuji. B.Tech. Executive Engineer (R&B) (R&B) Division, Eluru.

To,
The Correspondent,
Bethesda High School,
Konnamgunta Road
Boravancha Village
Nuzvid Mandal,
Eluru District,

## Lr.No:259/Soundness Certificate/JA/2020, Dt:30/09/2024.

Sir,

Sub:-Works (R&B) Division, Eluru- Bethesda High School Konnamgunta Road Boravancha Village, Nuzvid Mandal in Eluru District-Soundness Certificate - Issued – Regarding.

Ref:-Request regarding the Soundness Certificate of Bethesda High School Konnamgunta Road Boravancha Village, Nuzvid Mandal in Eluru District, Dt.08.04.2024.

\*\*\*\*

With reference to above, it is informed that the RCC Roofed Building and AC Sheet Roofed shed of Bethesda High School Konnamgunta Road Boravancha Village, Nuzvid Mandal in Eluru Distric is structurally sound to run the classes for a period of one year i.e. form 24.09.2024 to 23.09.2025.

Enclose: Soundness Certificate

Yours faithfully,

Executive Engineer (R&B) (R&B) Division, Eluru.

Haraha

## SOUNDNESS CERTIFICATE

1	Name of the School & Address	BETHESDA HIGH SCHOOL, KONNAMGUNTA ROAD, BORVANCHA VILLAGE, NUZVID MANDAL ELURU DISTRICT
2	Name of the Management and Phone number	BANDI.SYAM BHUSHAN, Correspondent Mob No:8142387777
3	Date of Inspection	24.09.2024
4	Year of Construction	2013
5	Type of the Building	RCC AND AC SHEET ROOF
6	Type of the foundation	Open foundation
7	Present Condition of foundation whether any settelement cracks are observed upto basement level	Not Observed
8	Soundness of superstructure whether any cracks out of plumb in walls noticed	Minor repairs to be Attended
9	Soundness of Girders, Trusses etc	Structurally sound
10	Condition of the Roofing	Structurally sound
11	Condition of Roof sheets, GI Sheet etc	Structurally sound
12	Any other remarks which are required to ensure the structural soundness	The inspection certificate does not covering all the aspects of the work and designs
13	/alid up to	23.09.2025
Ī	Note:	
1	1) Certificate is issued based on thepresent physical condition of the building. The management is responsible for the structure deformities which occur during course of time in future.  2) Further the management has to take necessary precautions during natural calamities occur from time to time for the safety of the students. (Such as cyclones severe weather conditions, Tsunamis, earthquakes etc.,)	
	Department is not responsible for any structural changes to the safety of the students. (Such as cyclones severe)	

Assi Exe Fugineer (R&B)
Section-1, Nuzvid

Deputy Exe Euglneer (R&B) Sub Division, Nuzvid

"Counter Signed"

Elective Engineer (R&B) Division, ELURU