

## Annexure D

### BUILDING SAFETY CERTIFICATE

No.

Dated: 30/09/2024

It is certified that the existing building Bethesda Integrated school (name of the building or premises) at Kannamgunta Road, Boravantha village, Nuzvid Eluru(DT), Andhra Pradesh (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G+2					

The building is owned/occupied by Bethesda Integrated school (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Roads & Buildings (Name of Department/ Govt.) on 24/09/2024 (date of inspection) in the presence of Bandi Syam Bhushanam, correspondent of school (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 24/09/2024 for a period of 1 year years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on 30/09/2024 at Eluru by

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

1)

Signature with Seal :

Executive Engineer

Name: Y. V. Lakshmi

Designation: Executive Engineer

Name & Address of Department/ Office: R&B Division, Eluru

2) DEPUTY EXECUTIVE ENGINEER (R&B)

GOVERNMENT OF ANDHRA PRADESH  
ROADS AND BUILDINGS DEPARTMENT

From,  
Sri.Y.V.Kishore Babuji. B.Tech.  
Executive Engineer (R&B)  
(R&B) Division, Eluru.

To,  
The Correspondent,  
Bethesda High School,  
Konnamgunta Road  
Boravancha Village  
Nuzvid Mandal,  
Eluru District,

Lr.No:259/Soundness Certificate/JA/2020, Dt:30/09/2024.

Sir,

**Sub:-**Works (R&B) Division,Eluru- Bethesda High School Konnamgunta Road  
Boravancha Village, Nuzvid Mandal in Eluru District-Soundness  
Certificate - Issued – Regarding.

**Ref:-**Request regarding the Soundness Certificate of Bethesda High School Konnamgunta  
Road Boravancha Village, Nuzvid Mandal in Eluru District, Dt.08.04.2024.

\*\*\*\*\*

With reference to above, it is informed that the RCC Roofed Building and AC Sheet  
Roofed shed of Bethesda High School Konnamgunta Road Boravancha Village, Nuzvid Mandal  
in Eluru Distric is structurally sound to run the classes for a period of one year i.e. form  
24.09.2024 to 23.09.2025.

Enclose: Soundness Certificate

Yours faithfully,

*[Signature]*  
30/9/24  
Executive Engineer (R&B)  
(R&B) Division, Eluru.  
*[Signature]*  
30/9/24

*[Signature]*  
PRINCIPAL  
BETHESDA HIGH SCHOOL  
Konnamgunta Road, BORAVANCHA (V)  
Nuzvid Mandal, PIN - 521 201

*[Signature]*  
CORRESPONDENT  
BETHESDA HIGH SCHOOL  
Konnamgunta Road, BORAVANCHA (V)  
Nuzvid Mandal, PIN - 521 201

## SOUNDNESS CERTIFICATE

1	Name of the School & Address	BETHESDA HIGH SCHOOL, KONNAMGUNTA ROAD, BORVANCHA VILLAGE, NUZVID MANDAL, ELURU DISTRICT
2	Name of the Management and Phone number	BANDI.SYAM BHUSHAN, Correspondent Mob No:8142387777
3	Date of Inspection	24.09.2024
4	Year of Construction	2013
5	Type of the Building	RCC AND AC SHEET ROOF
6	Type of the foundation	Open foundation
7	Present Condition of foundation whether any settlement cracks are observed upto basement level	Not Observed
8	Soundness of superstructure whether any cracks out of plumb in walls noticed	Minor repairs to be Attended
9	Soundness of Girders, Trusses etc	Structurally sound
10	Condition of the Roofing	Structurally sound
11	Condition of Roof sheets, GI Sheet etc	Structurally sound
12	Any other remarks which are required to ensure the structural soundness	The inspection certificate does not covering all the aspects of the work and designs
13	Valid up to	23.09.2025
<b>Note:</b> 1) Certificate is issued based on the present physical condition of the building. The management is responsible for the structure deformities which occur during course of time in future. 2) Further the management has to take necessary precautions during natural calamities occur from time to time for the safety of the students. (Such as cyclones severe weather conditions, Tsunamis, earthquakes etc.) 3) Department is not responsible for any structural changes to the building in future course of time.		

24/9/24  
Asst Exe Engineer (R&B)  
Section-I, Nuzvid

24/9/24  
Deputy Exe Engineer  
(R&B) Sub Division, Nuzvid

PRINCIPAL  
BETHESDA HIGH SCHOOL  
Konnamgunta Road, BORAVANCHA (V)

"Counter Signed"

24/9/24  
Executive Engineer  
(R&B) Division, Eluru

CORRESPONDENT  
BETHESDA HIGH SCHOOL